# Steps to work with Anea's digital height and weight measuring device


Placement on the scale

Carrying out weighing operations

Height measurement automatically

Display height, weight and BMI on the screen

Reporting by scanning the QR code of the display and registering in the Anea Cloud system



220

210

200

190

170

160

150

140

130

120

110

100


90


80

70

60

## **Anea Cloud Software**







# Anea Cloud system

- Unlimited storage of performed analysis
- Show the health status of the person
- . Chart of height, weight and BMI changes
- . The ability to create a user profile
- Display BMI (body mass index)
- Weight display
- Display BMR (Basal Metabolism)
- Height display
- Body norm charts

# Different parts of the software

#### BMI (body mass index):

- Graph of individual BMI changes in different periods of time
- . BMI display and analysis

### Display weight:

- · Analyzing the individual's weight and displaying the ideal weight
- Chart of weight changes

#### height display:

- Analysis of a person's height compared to other people of the same gender and age
- Chart of height changes

### Show BMR

